

## **Release Notes - SynScan Ver. 4.39.10 Firmware**

### **What's new in this update?**

1. Corrected the key-pressed slewing speed when key pressed in Rate 1 to Rate 8 in Alt/Dec axis, especially for mounts that have different gear ratios in both axes.
2. Fixed the issue for older version of SynScan GPS, for which the Week Rollover showed the year 2099 or the previous year.
3. Fixed the problem of PEC not working for those equatorial mounts without PPEC capability, such as the Sirius EQ-G.
4. Minor bug fixes.